DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-021699 Address: 333 Burma Road **Date Inspected:** 13-Mar-2011

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes An Qing Xiang. No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

Bridge No: 34-0006 **Component:** OBG components.

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance Inspector (QA) Mr. Shailesh Wadkar was present during the times noted above for observations relative to the fabrication of the Self Anchored Suspension (SAS) Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island, in Shanghai, China. QA Inspector observed and/or found the following:

Bay 14:

This QA Inspector observed the following work in progress:

OBG Seg 13AW:

The Flux Cored Arc Welding (FCAW) process on weld joint no: Seg3013K-159 [I-rib stiffener (RS3435F) to side Panel (SP) 3102A, fillet weld at panel point (PP) 119-1500]. The welder is identified as 045143 and was observed welding in 2F position. ZPMC Quality Control (QC) was identified as Shen Jian Bo. The welding variables recorded by this QC appeared to comply with welding procedure specification (WPS): B-T-2132-ESAB.

OBG Seg 14W:

Repair welding of weld joint nos: Seg3020AV-012 [Floor Beam (FB) 3343A to Longitudinal Diaphragm (LD) 3048A, complete joint penetration (CJP) weld, at PP128.3]. The welder is identified as 051348 and was observed welding in the 4G position. Welding process was identified as Shielded Metal Arc Welding (SMAW). ZPMC QC

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

was identified as An Qing Xiang. The welding variables recorded by this QC appeared to comply with WPS: 345-SMAW-4G(4F)-FCM-Repair. Repair welding was done as per Welding Repair Report (WRR): 20393 Rev-0.

Repair welding of weld joint nos: Seg3020U-587 [Anchor Plate (AP) to LD, CJP weld, at PP126]. The welder is identified as 067588 and was observed welding in the 3G position. Welding process was identified as SMAW. ZPMC QC was identified as An Qing Xiang. The welding variables recorded by this QC appeared to comply with WPS: 345-SMAW-3G(3F)-FCM-Repair. Repair welding was done as per Critical Welding Repair Report (CWR): 2854 Rev-0.

The SMAW process on weld joint no: Seg3020K-028 [Sub Assembly (SA) 3410A to LD3048A, CJP weld at PP127.3]. The welder is identified as 051348 and was observed welding in 4G position. ZPMC QC was identified as An Qing Xiang. The welding variables recorded by this QC appeared to comply with WPS: B-T-2214-TC-U4b-FCM-1.

Notification no: 008535.

OBG Seg 14W:

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% of an area that has been previously tested and accepted by ZPMC QC personnel. This QA Inspector has generated MT report for this date. The members are identified as OBG components. The weld designations MT inspected are as follows:

- 1) DP3172-001-218 to 221, 226 to 229, 234 to 237, 242 to 245.
- 2) DP3173-001-263 to 266, 271 to 274.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable Contract documents.

Summary of Conversations:

No significant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang; phone: 15000422372., who represents the Office of Structural Materials for your project.

Inspected By:	Wadkar,Sailesh	Quality Assurance Inspector
Reviewed By:	Peterson,Art	QA Reviewer